



Product Discontinuance Notice - PDN 17_0046 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of ADN2882

Publication Date: 28-Jun-2017

Last Time Buy Date: 28-Jun-2017

Last Time Ship Date: 29-Jun-2017

Revision Description:

Initial Release

Reason For Discontinuance

Loss of manufacturing capability. The tester has become obsolete and ADI no longer has a test solution for this product.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com

Europe: PDN_Europe@analog.com

Japan: PDN_Japan@analog.com

Rest of Asia: PDN_ROA@analog.com

PDN 17_0046 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADN2882A-DF	ADN2882	None	N/A	No AC tester
ADN2882ACHIPS	ADN2882	None	N/A	No AC tester

Appendix A - PDN 17_0046 Revision History

Rev	Publish Date	Rev Description
Rev. -	28-Jun-2017	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1165

Layout Rev:2

Parent DocId:1133